

RIFF JTAG Error codes and troubleshooting Failed to receive answer to READ command.

Failed to receive answer to READ command.

This error happens mostly due to high RTCK/TCK sampling rate. If You're using "Sample at Max" RTCK settings, set RTCK to lower value, for example to 1MHz. If You're using Fixed TCK, set it to lower value.

RIFF JTAG Error codes and troubleshooting





This problem can be also caused by bad connection, or bad 20pin ribbon cable. In some cases a literan be due to faulty target device hardware.

Sample at 40 kHz Sample at 60 kHz Unique solution ID: #1046 Authorible gijoo kHz Last update: 2012-04-30 15:13 Sample at 400 kHz Sample at 800 kHz Sample at 1 MHz Sample at 2 MHz Sample at 3 MHz Sample at 4 MHz Sample at 6 MHz Sample at 8 MHz Sample at 9 MHz Page 2 / 2 Sample at 10 MHz (c) 2024 Legija <> | 2024-04-23 08:52 Sample at URL Mittps://faq.riffbox.org/content/4/47/en/failed-to-receive-answer-to-read-command.html

1.80V