RIFF JTAG Error codes and troubleshooting Error code 0x39 (0x3901)

2.7. Error code 0x39

Returned by the DCC Loader when it was executing an extended command and that command failed. Extended command's failure status is operation specific and is not relevant to communication problems.

Explanation:

Mostly happens with HTC phones when HTC partition is erased.

Solution:

Repair HTC partition during repair process:

Select Areas to be Repaired	Select Variables to be Repaired
	Repair Custom ID (CID):
Generic Resurrection	11111111
Use 1.13.0000 SPL Version	
Repair RECOVERY Zones (Kernel + Recovery)	Repair IMEI:
Repair HTC Partition	355067-04-523832

Unique solution ID: #1034 Author: Legija Last update: 2012-04-28 13:31