
## RIFF JTAG Error codes and troubleshooting Failed to receive answer to READ command.

Failed to receive answer to READ command.

This error happens mostly due to high RTCK/TCK sampling rate. If You're using "Sample at Max" RTCK settings, set RTCK to lower value, for example to 1MHz. If You're using Fixed TCK, set it to lower value.

## RIFF JTAG Error codes and troubleshooting





This problem can be also caused by bad connection, or bad 20pin ribbon cable. In some cases with the discussion of the cases of the cas

Sample at 40 kHz
Sample at 60 kHz
Unigue Solution ID: #1046
Authorial equipo kHz
Last update: 2012 04-30 15:13
Sample at 400 kHz
Sample at 800 kHz
Sample at 1 MHz
Sample at 3 MHz
Sample at 4 MHz
Sample at 6 MHz
Sample at 8 MHz
Sample at 9 MHz
Sample at 9 MHz
Sample at 10 MHz
Sample at 10 MHz
Cc) 2024

1.80V

Page 2 / 2

(c) 2024 Legija <> | 2024-04-23 22:13

Sample at URL https://faq.riffbox.org/content/4/47/en/failed-to-receive-answer-to-read-command.html