RIFF JTAG Error codes and troubleshooting

Error code 0x60

1.5. Error code 0x60

Returned by the JTAG shifter block when timeout happens. This is possible when RTCK mode is active and firmware waits for RTCK signal response for too long period of time.

Solution:

Reset target device power, or use fixed TCK value.

Unique solution ID: #1010
Author: Legija
Last update: 2012-04-28 12:42

(c) 2026 Legija <> | 2026-11-24 19:27
URL: https://faq.riffbox.org/content/4/11/en/error-code-0x60.html