RIFF JTAG Error codes and troubleshooting

ERROR: DCC Loader has reported Error Code = 0x35

This is returned by DCC loader in case that eMMC internal controller fails to write specific block. Usually it means that eMMC chip has failed, and can not be recovered by software means.
Solution is very simple - solder new eMMC chip, repartition it and repair bootloader.

Unique solution ID: #1064
Author: Legija
Last update: 2013-05-18 12:31

(c) 2026 Legija <> | 2026-11-23 06:25
URL: https://faq.riffbox.org/content/4/65/en/error-dcc-loader-has-reported-error-code-=-0x35.html