RIFF JTAG Error codes and troubleshooting

Error code 0x49

1.14 Error code 0x49

Returned by box’s firmware when some timeout happens during JTAG communication between box and target. Can happen due to erroneous connection, spontaneous connection errors, target’s malfunction, loose of power, etc – or in general – all those factors which may influence loss of synchronization between box and target.

#define CMD_RESP_JTAG_WRONG_RESPONSE 0x4A

#define CMD_RESP_JTAG_MEM_ACCESS_ABORT 0x4B

#define CMD_RESP_JTAG_MEM_HS_OVERFLOW 0x4C

#define CMD_RESP_JTAG_SYS_SPEED_FAILED 0x4D

#define CMD_RESP_JTAG_DCC_RX_NOT_READY 0x4E

#define CMD_RESP_JTAG_CANNOT_DETECT_NEXT_STOP 0x4F

#define CMD_RESP_JTAG_TARGET_HALTED 0x50

#define CMD_RESP_JTAG_POWER_FAILED 0x51

#define CMD_RESP_JTAG_UNLOCK_FAILED 0x52

Unique solution ID: #1018
Author: Legija
Last update: 2012-04-28 12:58

(c) 2026 Legija <> | 2026-11-24 19:27
URL: https://faq.riffbox.org/content/4/19/en/error-code-0x49.html