# RIFF JTAG Error codes and troubleshooting
# Error code 0x30

**2.7. Error code 0x30**

Returned by the DCC Loader when it fails to perform specific write protection unlock procedure on some memory chips when it is required to be done

Unique solution ID: #1027
Author: Legija
Last update: 2012-04-28 13:16