RIFF JTAG Error codes and troubleshooting

Error code 0x30

2.7. Error code 0x30

Returned by the DCC Loader when it fails to perform specific write protection unlock procedure on some memory chips when it is required to be done

Unique solution ID: #1027
Author: Legija
Last update: 2012-04-28 13:16

(c) 2026 Legija <> | 2026-11-24 19:27
URL: https://faq.riffbox.org/content/4/28/en/error-code-0x30.html