RIFF JTAG Error codes and troubleshooting

WARNING: Programming Error (0x25)

2.7. Error code 0x25

Returned by the DCC Loader when it fails to program part of flash memory. This is not an abnormal situation for NAND memories – bad blocks and pages are sometimes appear due to specific NAND memory's technology. User shall select how to handle block program error in the JTAG Manager – for this user must be familiar with bad blocks handling techniques in general.

Solution for NAND based devices:

Reffer to Error Code 0x24.

Solution for eMMC based devices: (Samsung i9100, Samsung N7000 and similar)

Replace eMMC memory chip.

Unique solution ID: #1028
Author: Legija
Last update: 2013-05-18 18:37

(c) 2026 Legija <> | 2026-11-23 06:16
URL: https://faq.riffbox.org/content/4/29/en/warning-programming-error-0x25.html