RIFF JTAG Error codes and troubleshooting

ERROR: DCC Loader has reported Error Code = 0x3E (0x007FFF 0x010000)

ERROR: DCC Loader has reported Error Code = 0x3E (0x007FFF <> 0x010000)

This is returned by DCC loader in case that eMMC internal controller fails to erase/write specific block. Usually it means that eMMC chip has failed, and can not be recovered by software means.

Solution is very simple - solder new eMMC chip, repartition it and repair bootloader.



Unique solution ID: #1048
Author: Legija
Last update: 2012-04-30 19:07

(c) 2026 Legija <> | 2026-11-23 06:16
URL: https://faq.riffbox.org/content/4/49/en/error-dcc-loader-has-reported-error-code-=-0x3e-0x007fff-0x010000.html