RIFF JTAG Error codes and troubleshooting

ERROR: Timeout while waiting for DCC Loader response.

ERROR: Timeout while waiting for DCC Loader response.

Returned by DCC loader, usually during write operations. There is number of reasons which can cause this error:

- RTCK/TCK sampling rate is too high
- Connection with target device is unstable
- Flash memory is malfunctioning

User should adjust the RTCK/TCK sampling rate and check connection. In some cases, memory chip (NAND/NOR/eMMC) needs to be replaced.

How to adjust RTCK and TCK in order:

(c) 2026 Legija <> | 2026-11-23 06:25
URL: https://faq.riffbox.org/content/4/55/en/error-timeout-while-waiting-for-dcc-loader-response.html

RIFF JTAG Error codes and troubleshooting



(c) 2026 Legija <> | 2026-11-23 06:25
URL: https://faq.riffbox.org/content/4/55/en/error-timeout-while-waiting-for-dcc-loader-response.html

RIFF JTAG Error codes and troubleshooting



Unique solution ID: #1054
Author: Legija
Last update: 2012-05-05 11:10

(c) 2026 Legija <> | 2026-11-23 06:25
URL: https://faq.riffbox.org/content/4/55/en/error-timeout-while-waiting-for-dcc-loader-response.html