RIFF JTAG Error codes and troubleshooting

Error code 0x81

1.1 Error code 0x81

Is returned by many routines which were accessing UART (for read or write) and UART port was unexpectedly closed by the Host (PC)

Solution:

Check USB cable, and close any comport monitoring software. PC suite softwares can cause this problem.

Unique solution ID: #1007
Author: Legija
Last update: 2012-04-28 12:35

(c) 2026 Legija <> | 2026-11-23 23:23
URL: https://faq.riffbox.org/content/4/8/en/error-code-0x81.html