

RIFF JTAG Error codes and troubleshooting

Error code 0x53

1.15. Error code 0x53

Returned by box's firmware in case of attempt to set instruction breakpoint on currently selected target while all h/w breakpoint slots are already busy. May happen when executing CMM script – when user tries to set too many breakpoints than is possible on the current target.

Unique solution ID: #1019

Author: Legija

Last update: 2012-04-28 12:59