

# RIFF JTAG Error codes and troubleshooting

## Error code 0x53

### 1.15. Error code 0x53

Returned by box's firmware in case of attempt to set instruction breakpoint on currently selected target while all h/w breakpoint slots are already busy. May happen when executing CMM script - when user tries to set too many breakpoints than is possible on the current target.

Unique solution ID: #1019

Author: Legija

Last update: 2012-04-28 12:59