

RIFF JTAG Error codes and troubleshooting

ERROR: Timeout while waiting for DCC Loader response.

ERROR: Timeout while waiting for DCC Loader response.


Returned by DCC loader, usually during write operations. There is number of reasons which can cause this error:

- RTCK/TCK sampling rate is too high
- Connection with target device is unstable
- Flash memory is malfunctioning


User should adjust the RTCK/TCK sampling rate and check connection. In some cases, memory chip (NAND/NOR/eMMC) needs to be replaced.

How to adjust RTCK and TCK in order:

RIFF JTAG Error codes and troubleshooting



RIFF JTAG Error codes and troubleshooting



Unique solution ID: #1054
Author: Legija
Last update: 2012-05-05 11:10