RIFF JTAG Error codes and troubleshooting Error code 0x43

1.8. Error code 0x43

Returned by the box's firmware when target HALT operation was performed on already halted target.

Solution:

Don't halt already halted target!



Unique solution ID: #1012

Author: Legija

Last update: 2012-04-28 12:45