

# **RIFF JTAG Error codes and troubleshooting**

## **Error codes 0x54, 0x55**

### **1.16. Error codes 0x54, 0x55**

May be returned by box during firmware update stage. These errors are severe and can happen due to box's h/w malfunction or erroneous USB communication with PC.

Unique solution ID: #1020

Author: Legija

Last update: 2012-04-28 12:59